

CG-EX,CG-LX,CG-FX/FXII,CG-60st,CG-SRII,CG-60SR/SL など ピンチローラー交換手順書 3


このたびは、ピンチローラー交換用キット (SPC-0746) をお買い上げいただきありがとうございます。

ピンチローラの交換時には、以下の部品を使用してください。


部品名称	数量	備考	部品名称	数量	備考
ピンチローラー	1		Eリング	1	湾曲していない方をお使い
止めネジ	2	交換時には使用しません。		ı	ください。
弓形 E リング	1	交換時には使用しません。	ワッシャー	2	

ピンチローラーを交換する

- 1 プロッタの電源を切り、クランプレバーを上げます。
- 2 ピンチローラーの下に紙を敷きます。
- **3.** 右側のEリングの閉じている側にテープを貼り、精密ドライバーで引っかけて外します。



- ▲ P・R 軸を水平に引き抜きます。
 - ワッシャーは無くさないように注意してください。(お使いの装置の生産時期によっては、ワッシャーが無いタイプもあります。)
 - ・ 状態によっては、軸が抜きにくかったり、入れにくい場合があります。
- **5.** P・R 軸を抜いた逆の手順でピンチローラーとワッシャーを入れ、 ラジオペンチなどで E リングを取り付けてください。
 - ワッシャーを入れるときは、ピンセットを使うと入れやすくなります。
 - 交換作業が終了しました。



お使いの装置の生産時期によっては、 ワッシャーが無いタイプもあります。



CG-EX,CG-LX,CG-FX/FXII,CG-60st,CG-SRII,CG-60SR/SL etc. Procedure Manual for Replacing Pinch Roller 3


Thank you very much for your purchasing our kit for replacing pinch roller (SPC-0746).

Use the parts below at replacing the pinch roller.


Part name	Quantity	Remarks	Part name	Quantity	Remarks
Pinch roller	1		- E-ring	1	Use the one that is not
Setscrew	2	Is not used at replacement.			curved.
Arched E-ring	1	Is not used at replacement.	Washer	2	

Replace the pinch roller

- Turn off the power supply of the plotter, and raise the clamp lever.
- 2 Put a piece of paper under the pinch roller.
- **3** Paste scotch tape on the closed side of the E-ring on the right, and remove it by hooking with a precision screwdriver.



- Pull out the P/R shaft horizontally.
 - Do not lose the washer. (Depending on the production time, the machine has no washer.)
 - Depending on the status, the shaft may be hard to be pulled out/ inserted.
- Insert the pinch roller and the washer in the reverse procedures of removing the P/R shaft. Attach the E-ring with a needle-nose plier etc.
 - When inserting the washer, it is easier for you to perform the work with tweezers.
 - This is the end of the replacing work.



 Depending on the production time, the machine has no washer.